

Superintendent of Highways Report

April 19, 2016

BRIDGE REPORT

Jefferson Ave. Bridge:

The bridge appears to be in good condition. All daily maintenance is done by the Village of Mamaroneck. No near term needs are foreseen at this time.

South Barry Ave. Bridge transversing Guion Creek:

The bridge appears to be in good condition. All daily maintenance is done by the Village of Mamaroneck. No near term needs are foreseen at this time.

South Barry Ave. Bridge transversing Otter Creek:

All the contracts for the maintenance project have been signed and the work has been scheduled. The cooperation of the weather and the tides is all that is needed. According to forecasts the temperatures required should be constant by the last week of the April or the first week of May. The tidal schedule also works in our favor during that period as well. Ahnemen/Kirby and myself will monitor the progress and report back to the council.

Continental Manor Foot Bridge:

The bridge appears to be in good condition. All general maintenance is done by the Town of Rye.

Hillside Ave. Bridge:

At this time, there have been no changes to the status of this structure. Any preliminary discussions between the three municipalities will take place later this year.

Short Street Bridge:

The bridge appears to be in good condition. All general and daily maintenance is done by the Village of Mamaroneck. No near term needs are foreseen at this time.

North Barry Ave. Extension Bridge:

The bridge appears to be in good condition. All daily and general maintenance is done by the Village of Mamaroneck. No near term needs are foreseen at this time.

CEMETERY REPORT

African American Cemetery:

The grounds are in good condition.

Guion Family Burial Grounds:

The grounds are in good condition.

Solomon Gedney Cemetery:

The grounds are in good condition

Stewart/Rogers Cemetery:

There has been no change in the status of this cemetery. I have been looking at some historical information to aid me in locating the markers, if they are still there. I will then have to put up a cemetery marker and mark the boundaries of this very small cemetery.

Respectfully Submitted

John De Crescenzo
Superintendent of Highways